



Dr. Ing. Leonardo Bonini INGEGNERIA della SICUREZZA, AMBIENTE e della QUALITA'



BULLETIN No. 1/ 2014

LEGISLATIVE DECREE NO. 81/ 08 - INAIL : OBLIGATION TO RE-EVALUATION OF SHOCK HAZARD TO BE CARRIED OUT IN COMPLIANCE WITH THE NEW NORM IEC 62305-2

INAIL announced that the lightning risk assessment , carried out with the previous version of the IEC , it should be evaluated as required by Legislative Decree 81/2008 and subsequent amendments (Articles 17 , 29 and 84) . That by virtue of the fact that from March 1, 2013 is in force, the new standard IEC 62305-2 . " In fact, for existing buildings , in which the evaluation was carried out under the former rules , " the employer will have to make again assessment in accordance with the IEC 62305 - 2 and if necessary will identify and implement the necessary protective measures to reduce the risk to values not higher than the tolerable from the norm . " the current edition of the standard was divided into parts depending on the content of the topics covered with the latest parties that entered into force on 02.12.2013 . The following rules :
CEI EN 62305-1 (CEI 81-10/1) - in force since 02.12.2013 : (General Principles) .
CEI EN 62305-2 (CEI 81-10/2) - in force since 01.03.2013 : (Risk Assessment) .
CEI EN 62305-3 (CEI 81-10/3) - in force since 2.12.2013 : (Physical damage to structures and life hazard for people) .
CEI EN 62305-4 (CEI 81-10/4) - in force since 2.12.2013 : (Electrical and electronic structures) .

The Studio Dr. Ing. Leonardo Bonini is available for the necessary assessment.

Bologna 09/01/2014

Studio Dr. Ing. Leonardo Bonini



Intertek

STUDIO CERTIFICATO UNI EN ISO 9001:2008



Value Quality. Delivered.

Certificato No. 1215872

Via Galliera n°34, 40121 BOLOGNA Tel.: +39 051 240 241-FAX: +39 051 716 032 3 E-mail: bonini.leonardo@tiscali.it

Web: www.leonardobonini.com